




Turn Problem Areas into

CASE STUDY: The VanZoest Residence



Problem:

The VanZoest's wanted to turn their 1970's master bath into a more modern, functional living space. The tub/shower unit was too small and fighting over the one sink in the room was a daily occurrence. The side window was great for letting in natural light, but provided no privacy. The room also doubled as the family's laundry room, thus the bulky washer and dryer took up valuable space in the corner. Then, if that

weren't enough of a spacial dilemma, there was a large radiator heater in the bath that could not be moved.





THE DEHAAN REMODELING SPECIALIST

Solution:

Window is covered on the inside.

After

- The older, combo tub/shower was replaced with a deluxe ceramic stall shower with custom glass enclosure. Three spray options and a bench seat are included.
- The single sink was replaced by separate lavatory sinks on opposite walls. Granite counter tops compliment the heated ceramic tile floor. The new shower and sink were strategically positioned around the existing radiator to minimize it's presence.

The stackable washer and dryer unit was moved over and surrounding cherry cabinetry, complete with a clothes hamper, was incorporated to save on space. The historical committee would not allow us to eliminate the side window from the exterior, so we covered the window on the interior side and created a shadow box effect to achieve the privacy the family desired. The window is still on the side of the house and no one is the wiser.



Having any type of work done to your house disrupts your daily routine. At DeHaan Remodeling Specialists, our goal is to keep any inconvenience to you and your family at an absolute minimum. We use the utmost care when removing old construction materials and always clean up the work space at the end of each day.



This past February, a master bedroom/ bath remodeling project we were working on was in a hard to access area on the second floor. There was a large front window in the master bedroom that was also being replaced during the remodel project. We constructed a set of stairs up to the bottom of the window that allowed us to step through the window into the master bedroom area. This eliminated the need to protect all of the floors throughout the house and saved the client money by us not having to take as many steps from our trucks to the work area. The family appreciated keeping the main floor free of construction traffic and the additional cost savings.



TRUSTED, CERTIFIED SPECIALISTS SINCE 1978



DEHAAN SPECIALISTS, INC.







The craftsmen at DeHaan Remodeling Specialists have been known for creating exceptional Room Additions and Kitchen and Bath remodels for the past 30 years. But our home improvement services don't end there. Did you know we also do:

- Built-In Mantles & Shelving
- Pool Patios & Decks
- Laundry Rooms
- Front Facade (Siding & Trim)
- And Much More!

Don't Move...Improve!





Before

After

Bob DeHaan is a Certified Graduate Remodeler and a Certified Aging-In Place Specialist. Designated by the National Home **Builders Association.**





343-3757 • www.DeHaanRemodeling.com